




WIRING DIAGRAM.


Connect the internal & External units using a suitable 4-core cable.



LINK WIRE 4 CORE CABLE.

(Use suitable cable glands and seal to prevent any ingress of moisture).

INSIDE
COLDROOM.



240V 50 Hz
MAINS INPUT